

INDOOR LAP POOL STATUS (11/20/24)

WHEN WE WENT TO START UP THE MOTOR AND SYSTEMS, THE MAIN MOTOR FROZE UP. THE VALVE THAT SHUTS THE WATER OFF AT THE PUMP IS ALSO MALFUNCTIONING...THE ONLY WAY TO REPLACE THE MAIN MOTOR IS TO DRAIN THE POOL LOW ENOUGH FOR US TO PLUG THE DRAINS AT THE BOTTOM OF THE POOL. WE ARE CURRENTLY WORKING ON THIS - TIMEFRAME IS STILL TBD.

THANK YOU! - LCP MANAGEMENT